Sanitized Copy Approved for Release 2010/06/24 : CIA-RDP80T00246A041000080001-7

PROCESSING COPY

## INFORMATION REPORT INFORMATION

## CENTRAL INTELLIGENCE AGENCY

	S.E.C.R.E.	<b>∍</b> T		25 <b>X</b> 1
COUNTRY	East Germany	REPORT		
SUBJECT	Reconstruction Work at Stendal Airfield	DATE DISTR. 6 MAP 1958 NO. PAGES 1.		
		REFERENCES	RD	
DATE OF NFO. PLACE & DATE ACQ.				25>
)ATE ACW.	SOURCE EVALUATIONS ARE DEFINITIVE. A	PPRAISAL OF CONTEN	IT IS TENTATIVE.	25>
	gives information on the runway, ta field. A sketch showing the final included.	xiways and hards lay-out of these	standings at Ster	rt which ndal air- is also
	Tuganden.			
				051/4
				25 <b>X</b> 1
				25 <b>X</b> 1
				25 <b>X</b> 1
				25 <b>X</b> 1
		-		25X1
		·		25X1
				25X1
		·		25X1
				25X1
	S-B-C-R-E	<b>-T</b>		25X1

INFORMATION REPORT INFORMATION REPORT
Sanitized Copy Approved for Release 2010/06/24 : CIA-RDP80T00246A041000080001-7

Sanitized Copy Approved for Release 2010/06/24: CIA-RDP80T00246A041000080001-7 SE BUTTO East Germany AIR/MILITARY Airfield reconstruction - Progress as on 20 January 1958 Map References: 25X1 1:25000 Appendix: Attached as Appendix "A" is a scale plan showing the completed lay-out of the runway. taxiways and hardstandings, with confirmed measurements. At Appendix "A" is a scale plan showing the final lay-out of the completed runway/taxiway/hardstanding system on Stendal airfield. During December 1957 and January 1958 a total of 115 concrete sections from the runway, taxiways and hardstandings at Stendal airfield were taken up and re-laid. This was insisted on by Russian inspecting engineers after what had at first appeared to bd only small superficial oracks had been shown in fact to have penetrated right through the thickness of the concrete. The cause of these cracks is not known, but is not thought to be frost. It is no lenger intended to build a new fuel storage installation on the site hitherte occupied by the concrete mixers and ancillary equipand workmen have now started filling in the area already

25X1 ment excavated for this purpose. The reason given to the foremen of the building firm engaged on the site for this change of plan was that the proposed site was unsuitable since it was already known about in the West. It was said at the same time that the old Luftwaffe fuel depots would be brought back into use.

Sanitized Copy Approved for Release 2010/06/24: CIA-RDP80T00246A041000080001-7

SERET

25X1

25X1

25X1

